

Carver Elementary School (Initial Testing)
3325 Bell Avenue
St. Louis, Missouri 63106

Date of Sampling: July 7, 2016

Number of Samples Collected: 8
Number of Samples > 20 ppb: 0
Number of Samples > 10 ppb: 2

Sample ID #	Sample Source	Sample Location	Reporting Limit	Result	Priority
01	Fountain	1 st Floor South High	1.0 ppb	< 1.0 ppb	Priority 3
02	Fountain	1 st Floor South Low	1.0 ppb	4.4 ppb	Priority 3
03	Fountain	1 st Floor North High	1.0 ppb	4.9 ppb	Priority 3
04	Fountain	1 st Floor North Low	1.0 ppb	5.9 ppb	Priority 3
05	Fountain	1 st Floor East	1.0 ppb	5.1 ppb	Priority 3
06	Fountain	Near Room 101	1.0 ppb	12.3 ppb	Priority 2
07	Fountain	2 nd Floor Across Utility Closet	1.0 ppb	12.6 ppb	Priority 2
08	Sink	Kitchen	1.0 ppb	1.5 ppb	Priority 3

CONTINUED ON NEXT PAGE

Carver Elementary School (Re-Sampling Room 101 and 2nd Floor North)
3325 Bell Avenue
St. Louis, Missouri 63106

Date of Sampling: July 28, 2016

Number of Samples Collected: 4

Number of Samples > 20 ppb: 1

Number of Samples > 10 ppb: 0

Sample ID #	Sample Source	Sample Location	Reporting Limit	Result	Priority
01	Fountain	Room 101	1.0 ppb	4.6 ppb	Priority 3
02	Sink	Room 101	1.0 ppb	22.9 ppb	Priority 1
03 (Re-Sample of Sample #06)	Fountain	Near Room 101	1.0 ppb	7.1 ppb	Priority 3
04 (Re-Sample of Sample #07)	Fountain	2 nd Across Utility Closet	1.0 ppb	8.7 ppb	Priority 3