

Compton Drew Middle School (Initial Site Visit)
5130 Oakland Avenue
St. Louis, Missouri 63110

Date of Sampling: July 20, 2016

Number of Samples Collected: 13

Number of Samples > 20 ppb: 1

Number of Samples > 10 ppb: 0

Sample ID #	Sample Source	Sample Location	Reporting Limit	Result	Priority
01	Fountain	Near Room S101 High	1.0 ppb	< 1.0 ppb	Priority 3
02	Fountain	Near Room S101 Low	1.0 ppb	< 1.0 ppb	Priority 3
03	Sink	Kitchen	1.0 ppb	24.6 ppb	Priority 1
04	Fountain	Cafeteria High	1.0 ppb	< 1.0 ppb	Priority 3
05	Fountain	Cafeteria Low	1.0 ppb	< 1.0 ppb	Priority 3
06	Fountain	Near Room 100 High	1.0 ppb	< 1.0 ppb	Priority 3
07	Fountain	Near Room 100 Low	1.0 ppb	< 1.0 ppb	Priority 3
08	Fountain	Near Room 200 High	1.0 ppb	< 1.0 ppb	Priority 3
09	Fountain	Near Room 200 Low	1.0 ppb	5.0 ppb	Priority 3
10	Fountain	Near Room 305 High	1.0 ppb	< 1.0 ppb	Priority 3
11	Fountain	Near Room 305 Low	1.0 ppb	< 1.0 ppb	Priority 3
12	Fountain	Near Room 300 High	1.0 ppb	< 1.0 ppb	Priority 3
13	Fountain	Near Room 300 Low	1.0 ppb	< 1.0 ppb	Priority 3

Compton Drew Middle School (Re-Sample Kitchen)
5130 Oakland Avenue
St. Louis, Missouri 63110

Date of Sampling: July 28, 2016

Number of Samples Collected: 2
Number of Samples > 20 ppb: 0
Number of Samples > 10 ppb: 2

Sample ID #	Sample Source	Sample Location	Reporting Limit	Result	Priority
01 (Re-Sample of #03 Sample)	Sink	Kitchen Large	1.0 ppb	10.5 ppb	Priority 2
02 (Re-Sample of Sample #03)	Sink	Kitchen Small	1.0 ppb	10.1 ppb	Priority 2

Compton Drew Middle School (Re-Sample Kitchen Sink)
5130 Oakland Avenue
St. Louis, Missouri 63110

Date of Sampling: August 6, 2016

Number of Samples Collected: 2
Number of Samples > 20 ppb: 0
Number of Samples > 10 ppb: 0

Sample ID #	Sample Source	Sample Location	Reporting Limit	Result	Priority
01 (Re-Sample of Samples #03 and #01)	Sink	Kitchen Large	1.0 ppb	2.4 ppb	Priority 3
02 (Re-Sample of Sample #02)	Sink	Kitchen Small	1.0 ppb	2.8 ppb	Priority 3