

Laclede Elementary School (Initial Site Visit)  
 5821 Kennerly Avenue  
 St. Louis, Missouri 63112

Date of Sampling: June 30, 2016

Number of Samples Collected: 11  
 Number of Samples > 20 ppb: 1  
 Number of Samples > 10 ppb: 1

Sample ID #	Sample Source	Sample Location	Reporting Limit	Result	Priority
01	Fountain	2 <sup>nd</sup> Floor East	1.0 ppb	< 1.0 ppb	Priority 3
02	Fountain	1 <sup>st</sup> Floor East	1.0 ppb	4.1 ppb	Priority 3
03	Fountain	1 <sup>st</sup> Floor West	1.0 ppb	< 1.0 ppb	Priority 3
04	Fountain	Basement South West Wall	1.0 ppb	67.8 ppb	Priority 1
05	Fountain	Basement North West High	1.0 ppb	2.5 ppb	Priority 3
06	Fountain	Basement West Low	1.0 ppb	3.9 ppb	Priority 3
07	Sink	Kitchen	1.0 ppb	8.5 ppb	Priority 3
08	Fountain	Basement East Wall	1.0 ppb	9.6 ppb	Priority 3
09	Fountain	Basement East High	1.0 ppb	1.3 ppb	Priority 3
10	Fountain	Basement East Low	1.0 ppb	12.6 ppb	Priority 2

Laclede Elementary School (Re-Sample Basement and Kitchen)  
 5821 Kennerly Avenue  
 St. Louis, Missouri 63112

Date of Sampling: July 28, 2016

Number of Samples Collected: 3  
 Number of Samples > 20 ppb: 1  
 Number of Samples > 10 ppb: 1

Sample ID #	Sample Source	Sample Location	Reporting Limit	Result	Priority
01 (Re-Sample of Sample #04)	Fountain	Basement South West Wall	1.0 ppb	437 ppb	Priority 1
02 (Re-Sample of Sample #10)	Fountain	Basement East Low	1.0 ppb	1.4 ppb	Priority 3
03 (Re-Sample of Sample #07)	Sink	Kitchen	1.0 ppb	10.8 ppb	Priority 2